## APPENDIX D

PHOTOGRAPHS OF MOBY DICK CHANDLER - PHASE 2


117 Union St. – Phase 2 – Rehabilitation of the "Moby Dick" Building
Application for Certificate of Appropriateness
New Bedfod Historical Commission

## **PHOTOGRAPHS**



UNION STREET (SOUTH) ELEVATION

127-129 UNION ST., NEW BEDFORD, MA – APPLICATION FOR CERTIFICATE OF APPROPRIATENESS



BARKER'S LANE (NORTH) ELEVATION

127-129 UNION ST., NEW BEDFORD, MA – APPLICATION FOR CERTIFICATE OF APPROPRIATENESS




LOOKING SOUTHWEST FROM CORNER OF BARKER'S LANE AND 2<sup>ND</sup> STREET

## 127-129 UNION ST., NEW BEDFORD, MA – APPLICATION FOR CERTIFICATE OF APPROPRIATENESS





**DETERIORATED TERRA COTTA** 



**EXISTING IN-SWING CASEMENT WINDOW** 

## 127-129 UNION ST., NEW BEDFORD, MA – APPLICATION FOR CERTIFICATE OF APPROPRIATENESS



WINDOW DETAIL SIMILAR TO PROPOSED



ENTRY DOOR DETAIL SIMILAR TO PROPOSED