


**FRANK CORP.**  
**ENVIRONMENTAL SERVICES**

615 Tarkiln Hill Road  
New Bedford, MA 02745



TOLL FREE: 1 (877) ER-SPILL  
[1 (877) 377-7455]  
FAX: (508) 995-0002

---

**24 Hour Emergency Response**

Office: (508) 995-9997

August 3, 2017

Kathy Downey  
Trio-Algarvio Seafood, Inc.  
Green & Wood Pier  
New Bedford, MA 02740

Dear Kathy Downey,

This letter serves to document the inspection of an industrial oil and water separator and sediment trap located at Green & Wood Pier, New Bedford, MA.

On August 1, 2017, Frank Corp. Environmental Services conducted an inspection of one (1) oil and water separator and sediment trap also known as the Septor system. Frank Corp observed no significant solids at the bottom, or oil phase on top. The separator appeared to be in working order, and in good condition. The catch basins had been cleaned by the maintenance crew on site.

Thank you for choosing Frank Corp Environmental Services to complete this project. Please contact me should you have any questions.

Regards,  
Frank Corp. Environmental Services

A handwritten signature in black ink that reads "Kirk Franklin".

Kirk Franklin  
President