



ENGINEERING | SITEWORK | LAND SURVEYING | DEVELOPMENT

Servicing the Northeast

December 8, 2022

Conservation Commission City of New Bedford 133 William Street New Bedford, MA 02740

RE: Request for Certificate of Compliance 107 Welby Road New Bedford, MA 02745 DEP File No. SE49-337

Dear Commission Members:

This letter is to certify that we have visited the subject property in August/September 2021 to perform an existing conditions survey and visual inspection of the construction activities that took place approximately twenty years ago. As part of the survey the wetland resource areas on site were delineated by Environmental Consulting & Restoration, LLC in May 2021. As a result of the field survey a Certified Plot Plan was prepared to depict current site conditions. Upon review of the current site conditions it appears that the construction that took place did not encroach or have a negative impact on the resource areas however a Site Plan of the proposed work approved in the Order of Conditions could not be located to certify with certainty. We request that the Commission issue a Certificate of Compliance based on the information available at this time and provided.

Should you have any questions, or need any additional information, please do not hesitate to contact this office.

Very truly yours,

FARLAND CORP

Christian A. Farland, P.E., LEED AP Principal Engineer and President

cc. client, file