

C.E. Beckman Co. Stone Building Images [D] South Elevation 1



[D] South Elevation 2



[C] Asphalt Roof



[D] Industrial Metal Doors 1



[E] Store Front Elevation

Eighteen & Union Photo Log

10 Front Street, 11 and 35 Commercial Street, New Bedford, MA 02740



[F] Store Front Wood Shelving 1



[F] Store Front Wood Shelving 2



Door and Window Configuration 1



C.E. Beckman Co. Frame Building Images [A] South-East Elevation



C.E. Beckman Co. Frame Building Images 2 South Elevation




Frame Building Images 3 Proposed Elevated Roof View

Eighteen & Union Photo Log 10 Front Street, 11 and 35 Commercial Street, New Bedford, MA 02740



Frame: Bowing Ceiling, Sloping Floors 1




Frame: Foundation 1

Eighteen & Union Photo Log 10 Front Street, 11 and 35 Commercial Street, New Bedford, MA 02740



Frame Hoisting Equipment, Braced Framing 1



Fram ca. 1900 East Storefront Elevation 1

Eighteen & Union Photo Log 10 Front Street, 11 and 35 Commercial Street, New Bedford, MA 02740



Frame - Windows || Doors Configuration 1



Frame - Loading Bay Door 1

Eighteen & Union Photo Log



Frame Automobile Garage Door 1



The National Club Building Images – Previous Rolled Asphalt Roof (was replaced with new rolled rubber roof Summer 2019)




Second Floor Structure 1



National: Basement, Structure 1



National: North Elevation 1



Second Floor Front Facade Interior 1- Floor now dry after new roof installed

Eighteen & Union Photo Log 10 Front Street, 11 and 35 Commercial Street, New Bedford, MA 02740



National: First Floor historic bar 1



Existing metal sills to be restored 1

Eighteen & Union Photo Log

10 Front Street, 11 and 35 Commercial Street, New Bedford, MA 02740



National Club Historic Sign Union St. 1



National: Front wood doors to be restored